

[Link to valve lash article.](#)

[LINK TO 312 MAIN SEAL ARTICLE](#)

Image of oil filter adapter from Y Block engine being reformed so it will seal tighter against the gasket

When placed on a flat surface the center hole should be up about 1/16" from surface so that when it is secured in place much force will be exerted upon the gasket



55 T Bird distributor modified to Ford Duraspark ignition. Note that the larger distributor caps fits OK



plate for bolting the fuel bowl down in order to straighten it by heating

Checking the economizer diaphragm for leaks

Image of a 6V or 12V fuel sender from a 55 or 56 T Bird. Note the burnishing tool in position for burnishing contacts. Oxidized contacts are most often all that is wrong with these sending units.



page created with [Easy Designer](#)